(USE ADDITIONAL SHEETS IF NECESSARY)

CPSC FOR NO. 182 (Revised 10/93)(Adapted for WP for Windows & HP Laserjet III Printer 10/93)

PRE-INCIDENT

The complainant purchased a new, under-the-counter toaster in June, 1995 from a retailer. The unit was installed by the complainant under the counter and kept plugged in. The toaster was kept clean. It was used everyday without incident until October, 1995 (exact date unknown).

INCIDENT

The complainant's 14 year old son placed a slice of bread in the toaster on "light" and within a few minutes saw flames inside the toaster.

POST-INCIDENT

The complainant's son smothered the flames with a dishtowel. There were no injuries. The family continued to use the unit without further incident until December, 1995, when the complainant's husband placed a slice of bread in the toaster on a light setting and several minutes later saw flames. He also smothered the flames with a dishtowel.

The flames seemed to be coming from the center of the unit but the complainant's family was unable to determined exactly where they came from. After the second incident, they removed the unit because it was a fire hazard. The complainant phoned the manufacturer and was referred to a local service center. The representative at the service center stated that there was nothing he could do for the consumer and she dropped the issue at that point.

PRODUCT IDENTIFICATION

Manufacturer: Black & Decker

Shelton, CT

Model: Spacemaker #T1000

Dealer: Lechmere

Manchester, CT

The toaster is a horizontal unit that can be installed under a counter. It is labeled in part, "***Spacemaker Optima***MODEL NO. T1000***HOUSEHOLD USE ONLY***BLACK & DECKER U.S. INC. SHELTON, CT 06484***UL LISTED 228E***".

PRODUCT STANDARDS

The toaster is UL listed 228E.

SAMPLE

96-800-1632 was collected from the complainant.

ATTACHMENTS

1 - Photographs
2 - C/R 96-800-1632

ACCIDENT INVESTIGATION REQUEST FORM



Document Number	<u> </u>	<u>П</u>		
Date of Incident 10/95	·	Category I.	D. <u>Se</u>	CTRR
Follow-Op Requested	Hazz	ard Analysis		Section
Type Follow-Op Requested	TELE	phone Call	<u>04</u>	On-Site
Headquarters Contact 7.70	minec	Harrid	2.0	
Assignment Message 0670				induct
	*747			o octor
				
				
		<u> </u>		
وروان والمراورة والمراورة والمراورة والمراورة والمراورة والمراورة والمراورة والمراورة والمراورة			•	
• • •				
				
· · · · · · · · · · · · · · · · · · ·		·	·	
	• .			
		· .		
		1-11 .		
erson(s) to Contact Doring	Zacco	aroell;		
				
·				
deline				
ideline				
deline 				
			£	
vested By RR			£	
vested By RR	CCC 714	l _G		

ナベーン

CPSC FORM 175 (9/89)

Region: EASTERN

1. NAME OF RESPONDENT 2. PHONE NO. (HOME) (WORK) Dorinne Zaccardelli 203-742-5212 203-657-2083 3. STREET ADDRESS 4. CITY STATE ZIP CODE 37 Pine Knoll Drive Coventry CT 06238 5. DESCRIBE INCIDENT OR HAZARD, INCLUDING DATA ON INJURIES 14-year-old son placed a slice of bread in toaster on light setting and several minutes later, son saw flames (height unknown) coming from inside of toaster. Toaster was clean prior to incident. Son smothered flames with a dish towel. Bread was completely burned but toaster had no visible damage. 960409 CCC 7/46 -cont-7.IF INJURY OR NEAR MISS OBTAIN AGE/SEX 8. IF VICTIM DIFFERENT FROM 6. DATE 0 Y/N OF RESPONDENT, PROVIDE NAME INCIDENTS AND DESCRIBE INJURY: 10/95 none RELATIONSHIP none 9. DESCRIPTION OF PRODUCT 10. BRAND NAME electric horizontal under-the-cabinet toaster Black and Decker Spacemaker 11. MFR/DISTRIBUTOR NAME, ADDR. & PHONE 12. MODEL, SERIAL NUMBERS Black and Decker Optima Horizontal Toaster; M# T1000 662 Silas Dean Highway Hartford, CT 06109 13. DEALER'S NAME, ADDRESS & PHONE 203-563-5800 unknown unknown 14. WAS THE PRODUCT DAMAGED, REPAIRED OR 15. PRODUCT PURCHASED NEW x MODIFIED? YES x NO IF YES, BEFORE DATE PURCHASED 6/95 AGE 4 mos. OR AFTER THE INCIDENT? after DESCRIBE: damaged: see narrative 16. DOES PRODUCT HAVE WARNING LABELS? IF SO, NOTE: unknown 17. HAVE YOU CONTACTED THE 18. IS THE PRODUCT STILL 19. MAY WE MANUFACTURER? YES \mathbf{x} AVAILABLE? YES x USE YOUR NAME NO IF NOT, DO YOU PLAN TO CONTACT IF NOT, ITS DISPOSITION WITH THIS THEM? YES x NO REPORT? YES x NO FOR ADMINISTRATION USE 20. DATE RECEIVED 21. RECEIVED BY (NAME & OFFICE) 22. DOCUMENT NO. 03/04/96 aec/HL H9630035A 23. FOLLOW-UP ACTION 24. PRODUCT CODE(S) 0234 DISTRIBUTION 26. ENDORSER'S NAME & TITLE CCH 3/4/1996

Jarrative Continued

12/95 Husband placed a slice of bread in toaster on light setting and several minutes later, he saw 4" high flames coming out of toaster's door. Foaster was clean prior to incident. Husband smothered flames with a dish towel. Bread was completely burned and toaster's outer white plastic covering surrounding door was discolored. Husband discontinued use of toaster and removed it from underneath kitchen cabinet because he feels it presents a fire hazard.

3/96 Consumer plans to call and explain incident to manufacturer.

UL listing unknown.

CPSC Source: TV

960409 CCC 7146

U.S. Consumer Product Safety Commission

AUTHORIZATION FOR RELEASE OF NAME

Thank you for assisting us in collecting information on a potential product safety problem. The Consumer Product Safety Commission depends on concerned people to share product safety information with us. We maintain a record of this information, and use it to assist us in identifying and resolving product safety problems.

We routinely forward this information to manufacturers and private labelers to inform them of the involvement of their product in an accident situation. We also give the information to others requesting information about specific products. Manufacturers need the individual's name so that they can obtain additional information on the product or accident situation.

Would you please indicate on the bottom of this page whether you will allow us to disclose your name. If you request that your name remain confidential, we will of course, honor that request. After you have indicated your preference, please sign your name and date the document on the lines provided.

	You are hereby authorized t the information collected o	o disclose my name and address wit n this case.	h
	My identity is to remain con	nfidential.	
(Signature)	ne Zacrasdell.	5-6-96 (Date)	

Act #1

9604090007146





Fig. 182 - Front of the






Fig.3-Back of todster




Fig. 4- Side of tobster

960409CCC7146




Fig. 5- Inside of unit




Fig. 6- Close-up of unit's toterior

9604090007146




Fig. 7 - Bont metal piece inside




Fig. 8 - Label on bottom of unit



SAVE THIS USE AND CARE BOOK

Spacemaker* Optima™ Horizontal Toaster



800-231-9786
QUESTIONS? Please call us TOLL FREE!

MODEL T1000

Trademark of General Electric Company, U.S.A.

760409CCC7146

U.S. Consumer Product Safety Commission SAMPLE COLLECTION REPORT							
1. Sample Flag	<u>-</u>	2. Date Collected 5/6/96	3. Sample Type Physical	e and	Mumber: 96-800-1632 Documentary		
4a Product Name TOASTER		4b Model T1000	4c NEISS 0234		5. Assignment Number 960409CCC7146		
6. Complete for Import Samples Port of Entry:			7. MIS 32626		8. Hours Activity 2 Travel 3		
Country of Origin: Entry No. and Date: Customs Contact:			9a Home RO FOER		9b Collecting RO FOER		
10. Sample Cost \$0.00	11. ln	voice Value of Lo \$0.00		12. 5	Bize of Lot Units 1 unt		
13. Manufacturer/Importer # BLA030 BLACK & DECKER SHELTON, CT 06484	14. St	nipper/Foreign Ma	nufacturer	Dealer/Import Broker#BLA03 RINNE ZACCARDELLI PINE KNOLL DR. /ENTRY, CT 06238			
16. Supporting documents attached: tnvoice No. and Date: Date Shipped: Shipping Record and Date:							
Affidavit Signer's name, title and date:	NO	NE					
7. Product Identification: Product is a horizontal toaster that is to be installed under a counter. It is labeled in part, "***Spacemaker Optima***BLACK & DECKER Horizontal Toaster***MODEL NO. T1000***HOUSEHOLD USE							
8. Reason for collection/analysis needed: FHSA CPSA FFA PPPA RSA unit caught fire while in use							
19. Summary of Field Screening: none							
20. Sample size/Method of Collection: 1 unit was collected from the consumer and stored in a locked trunk until it was identified as per 21 and officially sealed in a paper bag as per 22. It was packaged in a cardboard box for shipping.							
					en 5/8/96		
23a Sample delivered to: UPS		23b D 5/9/96		t/Rec	ord Sent to:		
25. Laboratory/Office: LSHL LSEL_	CI	RMCCA_X	Other.				
26. Remarks: attached: receipt for sample							
27. Related Samples: none							
28a Collector's name/title: 28b Collector's signa							
			b Reviewer's signature/date:				
Barred Cobing Serv. I	<u> </u>		_		are.		

PRODUCT IDENTIFICATION
ONLY***BLACK & DECKER U.S. INC. SHELTON, CT 06484***UL LISTED 228E
***".

960409 CCC 7/46

ADDENDUM TO IDI #960409CCC7146

Attached, is the owner's manual for the toaster oven involved in the above incident.

5/3